



The Standard

AIRCRAFT LOG

ARA-5A-1

The Standard Aircraft Log
SA-1

© 1993–2013 Aviation Supplies &

ASA-SA-1

ISBN 1-56027-419-0
978-1-56027-419-3

All rights reserved.
Reproduction or use, without express
in any manner, is prohibited.

Published by
Aviation Supplies & Academics, Inc.
7005 132nd Place SE, Newcastle,
Website: www.asa2fly.com Email,

Printed in the United States of America

02

CESSNA 150B ser# 15059607

3A19 TCD

Continental 0200-A 3159-2-A

McCauley propeller M/N 1A100 P/N MCM 6950

CESSNA 150B N ~~2107Y~~

15059607

1207

Y

CONTINENTAL 0200-A

3159-2-A



ISBN 978-1-56027-419-3



50595



YEAR 20____ DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
			03/01/2021	N1207Y C150S S/N15059607 tach1211.8 TT 5795.55 Annual inspection as per Cessna service manual, FAR 43, appendiix d, ELT checkas per 207 (d) ELT battery expires 12/2021, ck all ADs thru 03/2021 Replace carpet floor mat by AIRTEX ,NO CHANGE IN WT & BALANCE . I certify that this Aircraft has been inspected in accordance with annual inspection an has been found to be in airworthy condition . Arthur N.PATRUM A&P 3966953 IA

YE/
20
DAT



560 Berne Road | Columbia Falls | MT | 59912
www.uAvionix.com | Office: 1-844-827-2372

Model: tailBeacon TSO Installation Kit
P/N: UAV-1003202-001

uAvionix Corporation
tailBeacon TSO Installation Kit
TSO-C30c INCOMP
#4 Hardware
UAV-1003202-001

20210609-00

UAV-1003202-001 (Rev B)

Certificate of Conformance

I hereby certify that the product/s enclosed herewith, manufactured by uAvionix Corporation, have been inspected and found to be in full accordance with the specifications of:
TSO-C30c INCOMP

By: Wendy Ekmare

Date: 6/11/21

UAV-1003202-001 (Rev B)

Country of Origin: U.S.A.



560 Berne Road | Columbia Falls | MT | 59912
www.uAvionix.com | Office: 1-844-827-2372

Model: tailBeacon TSO
P/N: UAV-1002183-001

uAvionix
P/N: UAV-1002183-001
MOD: 2
S/N: 2018479

Certificate of Conformance

I hereby certify that the product/s enclosed herewith, manufactured by uAvionix Corporation, have been inspected and found to be in full accordance with the specifications of:
TSO-C154c B1S, TSO-C145e Beta 1 INCOMP, TSO-C88b, and TSO-C30c Type III.

By: ES

Date: 6/11/21

UAV-1003043-001 (Rev B)

Country of Origin: U.S.A.

Thank you for purchasing tailBeacon
Your Wi-Fi information is:



SSID: beacon-0030
Pass: tailBeacon

YEAR 2022 DATE 1-27-22	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
1-29-22	1229.83	Installed		GE4509 W Light, Replaced ELT Batteries checked per 207(d)
Next due	1/24	Replaced		Rotative Beacon Bulb BA455. Muel/Bone AIP 3207328

N1207Y Cessna 150B S/N 150-59607 5/1/2022 Tach 1233.98 TT 5817.73 Performed annual inspection per annual inspection instructions in Cessna service manual D138-13. Repacked wheel bearings. Replaced right main bearing race PN TMK 08125-20629. Installed Challenger CP-1150 air filter kit per STC instructions. Owner provided with 337 and submitted to FAA. Installed uAvionix Tailbeacon PN UAX-90036-01 IAW Tailbeacon installation manual. Fluids drained from aircraft and performed a new weight and balance by weighing the aircraft on certified scales IAW with instructions provided in the maintenance manual. New W&B and equipment list added to aircraft records. ELT inspected per 91.207(d), batteries next due 1/2024. AD compliance sheets in aircraft records dated 11/28/2015 are current with the following additional reoccurring inspection: C/W AD 2011-10-09 seat track inspection, visual inspection and measurements as specified in the AD. Other AD's screened thru 5/1/2022, no new AD's found and all reoccurring ADs have been complied with previously. I certify that this AIRFRAME has been inspected in accordance with an annual inspection and was found

