

Book # 1



FAA APPROVED REPAIR STATION #PZ4R458M  
Clark County Airport • Sellersburg, Indiana 47172  
(800) 356-3723

## PROPELLER MAINTENANCE LOG

MAKE McCauley

MODEL B2D34C211 / 82PA-6

PROPELLER HUB SERIAL NUMBER 750580

BLADE SERIAL NUMBERS K42806 K42809 \_\_\_\_\_



ACCUMULATED  
TOTAL

PROPELLER TIME

Hours 10ths

Description of Inspections and Repairs

Enter here general data with reference to "Line" and "Periodic" inspections - Rigging Changes - Alterations and Repairs. ALL DATA must be endorsed with the name, rating and certificate number of either the FAA Repair Station or the mechanic.

5/1/99	1406	22	tax 1406 reinstalled propeller after overhaul, check track, check operation found OK. Jeffrey S. [Signature] P2205907
5/1/99	2303		Dressed prop, painted back of prop flat black Richard [Signature] 1792283 AS
6/23/01	2686.0		Prop inspected and checked leadings etc and track David Waterman 1479850
9/20/01	2745		Overhauled propeller in accordance with McCawley Manual 780630 Rev 2. Complied with McCawley Bulletins 1979, 197B, 192A, 227A & Service Letters 1979-5, 1986-4, 1959-20, 1991-2, 1993-5, 1994-19A, 1998-5B, 1998-31, 1998-32C, 1999-5B, 2000-34 2000-8A. Maxwell Aircraft Service, Inc. Mpls, MN, CRSA#44F2R211L, Repair Order No 126162. C-199maxwell 2386511

MARKET FORWARD THE TOTAL ACCUMULATED FLYING TIME TO THE TOP OF NEXT PAGE