

PROPELLER MAINTENANCE RECORD

Propeller Manufacturer: McCawley

Hub Model No. B2D34C211

Hub Serial No. 743458

Blade Model No. 82 PCA-6

Blade Serial No. 1 Q 1182

No. 2 Q 1183

No. 3 h h h

No. 4 h h h

No. 5 _____

High 26.5° Low 12.1° PITCH RANGE Feather ~~~~ Reverse ~~~~

Governor Manufacturer: _____

Governor Model No. _____

Governor Serial No. _____

Maximum Hours or Service Life between overhaul recommended by Mfg. 2000 Hrs. or Six


whichever occurs first

CUSTODY RECORD

Owner _____	Date Rec'd. _____
Owner _____	Date Rec'd. _____
Owner _____	Date Rec'd. _____
Owner _____	Date Rec'd. _____


Aircraft Installed On:	Make/Model	Serial #
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

OVERHAUL RECORD

No.	Date	Repair Station and No.	Signature
	3-29-2002	<i>Executive Propellers, Inc.</i> 18140 Covello St., Van Nuys, CA FAA CRS # EU6R595N	

DESCRIPTIONS OF ALL OPERATIONS
 PERTAINING TO AIRWORTHINESS DIRECTIVES,
 SERVICE BULLETINS, SERVICE LETTERS,
 & MINOR ADJUSTMENTS

Annual 180630
 Steel and
 Blades 9
 Pa. Ca
 0800

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
3-29-2002	"0" S.P.O.H.	<p>PROPELLER COMPLETELY OVERHAULED, I.A.W. McCAULEY SERVICE MANUAL # <u>780630</u>, <u>604100-1</u>, <u>SP4100-1</u> ALL A.D.'s AND McCAULEY S.B.'s AND ⁷⁸⁰⁶³⁰ <u>AND</u> COMPLIED WITH TO DATE. <u>Retention details of this overhaul</u> <u>are on file under W.O. 02-134 at the following</u> <u>facility:</u></p> <p><u>Executive Propellers, Inc.</u> 16140 Covello St., Van Nuys, CA FAA CRS # EU6R595N</p>	
7-16-02	2792.8	<p>Installed on N3523Q this time and date. Ground run for leaks & performance ok.</p> <p>Steve J. Maglio AP471780408 JA</p>	

DEVIATIONS OF ALL OPERATIONS
 PERTAINING TO AIRWORTHINESS DIRECTIVES,
 SERVICE BULLETINS, SERVICE LETTERS,
 & MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
8/24/04	2922.4	I certify that this <u>Prop</u> has been inspected in accordance with <u>Annual</u> inspection and was determined to be in airworthy condition.	Richard Nerlis 1992283 FA
Oct 09-08	3037.4	I certify that this propeller has been inspected in accordance with an annual inspection and determined to be in airworthy condition	William J. Alby 1601433 FA.
Nov 13 2012	3107.0	Inspected propeller in accordance with an annual inspection and found airworthy at the time.	William J. Alby 1601433 FA.

**DESCRIPTIONS OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
NOV 13 2013	3116.3	I certify that this propeller has been inspected in accordance with an annual insp and found airworthy at this time.	William J. Alby
			1601433 FA

Propeller Log Entry For N3523Q

TACH: 3161.4 TSOH: 368.6 TTSN: 3161.54 DATE: 11-05-14

Remove spinner, inspect blades and hub. Dressed blades.

I certify this Propeller has been inspected IAW FAR 43 App D and was determined to be in airworthy condition.

Signed: Ryan Johnson

A&P# 31232761A

Johnson Bros Flying Service Tri-County Airport (INR) E2525 Co Hwy JJ Spring Green, WI 53588 (608)341-8030

NOV 10 th 2015	TACH 3161.4	I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IAW A 100HR INSPECTOR & WAS DETERMINED TO BE IN AIRWORTHY CONDITION.	
		<u>Ryan Johnson</u>	A&P# 31232761A

DESCRIPTIONS OF ALL OPERATIONS
 PERTAINING TO AIRWORTHINESS DIRECTIVES,
 SERVICE BULLETINS, SERVICE LETTERS,
 & MINOR ADJUSTMENTS


DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
------	-----------	---------------------	-----------

Propeller Log Entry for N3523Q

DATE: 11-23-16 TACH: 3,302.8 TTSN: 3,302.8 SMOH: 510

Remove spinner, inspect hub and dress blades

I certify this propeller has been inspected IAW a 100 HR inspection as per FAR PART 43 APP D and was determined to be in airworthy condition.

Signed: 

A&P 31232761A


Johnson Bros. Flying Service E2525 Co Hwy JJ Spring Green WI 53588 Tri County Airport (LNR) (608)341-8030

Propeller Log Entry for N3523Q

DATE: 12-12-17 TACH: 3,372.6 TTSN: ~~579.8~~ ^{3,372.6} SMOH: ~~579.8~~ ^{579.8} *of*

Remove spinner, inspect hub and dress blades. Cycle on engine run-up.

I certify this propeller has been inspected IAW a 100 HR inspection as per FAR PART 43 APP D and was determined to be in airworthy condition.

Signed: 

A&P 31232761A

Johnson Bros. Flying Service E2525 Co Hwy JJ Spring Green WI 53588 Tri County Airport (LNR) (608)341-8030

DAI
 Rem
 I cer
 JMM

DESCRIPTIONS OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
------	-----------	---------------------	-----------

Propeller Log Entry for N3523Q

DATE: 01-03-19 TACH: 3,389.4 TTSN: 3,389.4 TSOH: 596.6

Remove spinner, inspect hub and dress blades.

I certify this propeller has been inspected IAW a 100 HR inspection as per FAR PART 43 APP D and was determined to be in airworthy condition.

Signed: 

AP31232761A


Johnson Bros. Flying Service E2525 Co Hwy JJ Spring Green Wi 53588 Tri County Airport (LNR) (608)341-8030

PROPELLER LOG ENTRY N3523Q

DATE: 01-24-19 TACH: 3,389.4 TTSN: 3,400.9 TSOH: 581.1

Remove spinner, inspect hub and dress blades.

I certify this propeller has been inspected IAW a 100 HR inspection as per FAR PART 43 APP D and was determined to be in airworthy condition.

Signed: 

AP31232761A

Johnson Bros. Flying Service E2525 Co Hwy JJ Spring Green Wi 53588 Tri County Airport (LNR) (608)341-8030