

AIRCRAFT MAINTENANCE RECORDS

Owner ATLAS AVIATION


Aircraft Registration **N** 789SV

Manufacturer CESSNA 177RG
McCauley PROPELLERS

Model B2D34C207/78TCA-0

Serial No. 110491

Position _____



Atlas Aviation Tampa Inc.
825 Severn Ave. Tampa, FL. 33606
Tail No. N7895V Prop: B2D34C207/78TCA-0 SN; 110491 Tach: 3128.5 PropTT: 1336.5
W/O: SHP17-0042 Date: 19-APR-17

I certify that this Propeller has been inspected IAW a 100 hour inspection as per the minimum requirements in FAR Part 43 appendix D and MPC-26 and was determined to be in an airworthy condition.
No Applicable Ads to comply with at the time of this inspection.
Work performed to the aircraft and/or component(s) identified above performed IAW current FAA regulations and was found to be in airworthy with respect to the work performed.

 Thomas G. Renn A&P2774353-IA

K & K
PRECISION WELDING
near Hwy 1 Unit 15

 Atlas Aviation	N7895V Model:177RG S/N:177RG0913 Tach:3184.7 W/O:SHP17-0071	
	Removed Spinner for repair Facility and reinstalled serviceable with sucesful operation check IAW MPC and AMM manuals.	
	This Aircraft is Approved for return to service with respect to the work performed.	
	Atlas Aviation Inc. 825 Severn Ave. Tampa, FL 33606	
	 Thomas Renn AP2774353IA 22-Jun-17	

Atlas Aviation Tampa Inc. Propeller
825 Severn Ave. Tampa, FL. 33606
Tail No. N7895V Prop: B2D34C207/78TCA-0 SN; 110491 Tach: 3232.6 PropTT: 1896.1
W/O: SHP17-0087 Date: 20-JUL-17

I certify that this Propeller has been inspected IAW a 100 hour inspection as per the minimum requirements in FAR Part 43 appendix D and MPC-26 and was determined to be in an airworthy condition.
No Applicable Ads to comply with at the time of this inspection.
Work performed to the aircraft and/or component(s) identified above performed IAW current FAA regulations and was found to be in airworthy with respect to the work performed.

 Wiafe K. Manu-Anno 3257347-AP

_____ **SUB-TOTAL** THIS PAGE
_____ **TOTAL** - CARRY FORWARD TO NEXT PAGE

AIRCRAFT MAINTENANCE RECORD

Page No. _____

Date	Total Time	DESCRIPTION OF WORK PERFORMED SIGNATURE & CERTIFICATE NUMBER OF PERSON PERFORMING WORK
------	------------	---

Atlas Aviation Tampa Inc. Propeller
 825 Severn Ave. Tampa, FL. 33606
 Tail No. N7895V Prop: B2D34C207/78TCA-0 SN; 110491 Tach: 3321.6 Hobbs: 4054.6
 W/O: SHP17-0151 Date: 14-DEC-17

I certify that this Propeller has been inspected IAW a 100 hour inspection as per the minimum requirements in FAR Part 43 appendix D and MPC-26 and was determined to be in an airworthy condition.
 No Applicable Ads to comply with at the time of this inspection.
 Work performed to the aircraft and/or component(s) identified above performed IAW current FAA regulations and was found to be in airworthy with respect to the work performed.

 Thomas G. Renn 2774353AP-IA

Atlas Aviation Tampa Inc. Propeller
 825 Severn Ave. Tampa, FL. 33606
 Tail No. N7895V Prop: B2D34C207/78TCA-0 SN; 110491 Tach: 3364.2 Hobbs: 4102.8 TSMOH: 2116.5
 W/O: SHP18-012 Date: 14-FEB-18

I certify that this Propeller has been inspected IAW an Annual inspection as per the minimum requirements in FAR Part 43 appendix D and MPC-26 and was determined to be in an airworthy condition.
 No Applicable Ads to comply with at the time of this inspection.
 Work performed to the aircraft and/or component(s) identified above performed IAW current FAA regulations and was found to be in airworthy with respect to the work performed.

 Thomas G. Renn 2774353AP-IA

Atlas Aviation Tampa Inc. Propeller
 825 Severn Ave. Tampa, FL. 33606
 Tail No. N7895V Prop: B2D34C207/78TCA-0 SN; 110491 Tach: 3458.9 Hobbs: 4208.0
 W/O: SHP18-073 Date: 24-MAY-18



I certify that this Propeller has been inspected IAW a 100 hour inspection as per the minimum requirements in FAR Part 43 appendix D and MPC-26 and was determined to be in an airworthy condition.
 No Applicable Ads to comply with at the time of this inspection.
 Work performed to the aircraft and/or component(s) identified above performed IAW current FAA regulations and was found to be in airworthy with respect to the work performed.

 Jean C. Suchini AP3794398

		SUB-TOTAL THIS PAGE
		TOTAL - CARRY FORWARD TO NEXT PAGE

AIRCRAFT MAINTENANCE RECORD

Page No. _____


FC	Sarasota Avionics Inc Tampa (TPA) Prop		DRK
	845 Severn Ave. Tampa, FL 33606		
	Tail No: N7895V/McCauley/B2D34C207/78TCA-0/Serial: 110491		
	Date: 11/27/18 Work Order: M719		
	Tach: 3542.8 PROP TT: 1750.8		
	I certify that this propeller has had a 100 hour inspection IAW FAR43 Appendix D and was determined to be in an airworthy condition and is approved for return to service. All applicable airworthiness directives through 11/27/18 have been reviewed and/or complied with. List in logbook. Performed ground run up, all applicable leak and ops checks good.		
		Steven D. Reifeis A&P35055351A	

Atlas Aviation Tampa Inc. Propeller
825 Severn Ave. Tampa, FL 33606
Tail No. N7895V Prop: B2D34C207/78TCA-0 SN; 110491 Tach: 3626.0 Hobbs: 4395.3 TSMOH: 2378.3
W/O: SHP19-026 Date: 08-MAR-19

I certify that this Propeller has been inspected IAW an Annual inspection as per the minimum requirements in FAR Part 43 appendix D and MPC-26 and was determined to be in an airworthy condition.
No Applicable Ads to comply with at the time of this inspection.

Work performed to the aircraft and/or component(s) identified above performed IAW current FAA regulations and was found to be in airworthy with respect to the work performed.

 Thomas G. Renn 2774353AP-IA

Atlas Aviation Tampa Inc. <u>Propeller</u>	
825 Severn Ave. Tampa, FL 33606	
Tail No. N7895V Prop: B2D34C207/78TCA-0 SN: 110491 Tach: 3728 Prop TT: 2480	
W/O: SHP19-053 Date: 09-MAY-19	
I certify that this Propeller has been inspected IAW a 100 hour inspection as per the minimum requirements in FAR Part 43 appendix D and MPC-26 and was determined to be in an airworthy condition. No Applicable Ads to comply with at the time of this inspection. Work performed to the aircraft and/or component(s) identified above performed IAW current FAA regulations and was found to be in airworthy with respect to the work performed.	
	Chad M. Golden A&P 3950749

SUB-TOTAL THIS PAGE
TOTAL - CARRY FORWARD TO NEXT PAGE

AIRCRAFT MAINTENANCE RECORD

Page No. _____


Date	Total Time	DESCRIPTION OF WORK PERFORMED SIGNATURE & CERTIFICATE NUMBER OF PERSON PERFORMING WORK
------	------------	---

CARRIED FORWARD →

Atlas Aviation Tampa Inc. Propeller
 825 Severn Ave. Tampa, FL. 33606
 W/O: SHP19-085 Date: 02-AUG-19
 N7895V Prop: B2D34C207/78TCA-0 SN: 110491 Tach: ~~3800.3~~ 3830.3 Prop TT: 2632.6


3830.3 CMG

I certify that this Propeller has been inspected IAW a 100 hour inspection as per the minimum requirements in FAR Part 43 appendix D and MPC-26 and was determined to be in an airworthy condition.
 No Applicable Ads to comply with at the time of this inspection.
 Work performed to the aircraft and/or component(s) identified above performed IAW current FAA regulations and was found to be in airworthy with respect to the work performed.


 _____, Chad M. Golden A&P 3950749


Atlas Aviation Tampa Inc. Propeller
 825 Severn Ave. Tampa, FL. 33606
 W/O: SHP19-____ Date: 30-OCT-19
 N7895V Prop: B2D34C207/78TCA-0 SN: 110491 Tach: 3914.0 Prop TT: 2666.3

I certify that this Propeller has been inspected IAW a 100 hour inspection as per the minimum requirements in FAR Part 43 appendix D and MPC-26 and was determined to be in an airworthy condition.
 No Applicable Ads to comply with at the time of this inspection.
 Work performed to the aircraft and/or component(s) identified above performed IAW current FAA regulations and was found to be in airworthy with respect to the work performed.


 _____, Chad M. Golden A&P 3950749

Atlas Aviation Tampa Inc. Propeller
 825 Severn Ave. Tampa, FL. 33606
 W/O: SHP20-008 Date: 13-FEB-2020
 N7895V Prop: B2D34C207/78TCA-0 SN: 110491 Tach: 4004 Prop TT: 2756.3

I certify that this Propeller has been inspected IAW a 100 hour inspection as per the minimum requirements in FAR Part 43 appendix D and MPC-26 and was determined to be in an airworthy condition.
 No Applicable Ads to comply with at the time of this inspection.
 Work performed to the aircraft and/or component(s) identified above performed IAW current FAA regulations and was found to be in airworthy with respect to the work performed.


 _____, Chad M. Golden A&P 3950749

SUB-TOTAL THIS PAGE
TOTAL - CARRY FORWARD TO NEXT PAGE

AIRCRAFT MAINTENANCE RECORD

Page No. _____



N7895V Model:177RG S/N:177RG0913 Tach:4034 W/O:SHP20-039

ED
FORMING WORK

Removed Prop and sent for O/H. Reinstalled at zero time. Removed and replaced Governor. Run-up and leak checks good. Work performed IAW AMM. MPC-25 and SI 1438a

Atlas Aviation Inc.
825 Severn Ave.
Tampa, FL 33606

Dung Q. Tran A&P 3995053 5-MAY-2020

Atlas Aviation Tampa Inc.
825 Severn Ave. Tampa, FL 33606
W/O: SHP20-039 Date: 5-MAY-2020

Propeller

N7895V Prop: B2D34C207/78TCA-0 SN: 110491 Tach: 4034.2 Prop TSMOH: 0.1

I certify that this Propeller has been inspected IAW an Annual Inspection Checklist as per the minimum requirements in FAR Part 43 appendix D and MPC-26 and was determined to be in an airworthy condition.
No Applicable Ads to comply with at the time of this inspection.

Work performed to the aircraft and/or component(s) identified above performed IAW current FAA regulations and was found to be in airworthy with respect to the work performed.

Thomas G. Renn A&P2774353-IA

REG #	N7895V	LOGBOOK INSERT	DATE	7/03/2021
MODEL	Cessna 177RG			
SERIAL #	177RG0913			
Prop Model	B2D34C207/78TCA-0		TACH	4241.5
Prop S/N	110491		A/C TT	6160.5
Prop TT: 2993.8 TSO: 207.5 1. Completed a 100-hr inspection of the propeller. 2. I certify that this propeller has been inspected in accordance with a 100-hr inspection and was determined to be in airworthy condition at this time/date.				
The Aircraft identified above was repaired and/or inspected in accordance with current applicable Federal Aviation Regulations and were determined to be airworthy for return to service. DATE: 7/03/2021 SIGNED: A/P 476860448 IA Thomas W. Thunstrom A/P 476860448 IA				

SUB-TOTAL THIS PAGE