

# PROPELLER/ROTOR HISTORY

Propeller/Rotor  
Installed On:

ENGINE TYPE \_\_\_\_\_ MAKE AND MODEL AIRCRAFT \_\_\_\_\_  
 ENGINE SERIAL NUMBER \_\_\_\_\_ AIRCRAFT REGISTRATION NO. \_\_\_\_\_  
 POSITION ( If Multi-Engine Aircraft) \_\_\_\_\_ DATE INSTALLED \_\_\_\_\_

Date	Total Time	Time Since Major Overhaul	Repair Station and Number	Work Performed <span style="float: right;">95586-41 A Hogan</span>
2-10-82			A 982-27-R1 N-Abby Hub + Blade #	inspect blade shanks OK
5-20-85	Tac 4280		Visual check	OK! A Hogan 95586-41
6-18-86	Tac 7288	owner advised on time of Prop.	Visual check	OK! A Hogan 95586-41
10-7-87	Tac 4296		Visual check	OK! A Hogan 95586-41
9-9-88	Tack total		This Propoz. Currently Installed on Cessna 182	
	Tack 4302.97		182 J N# 498 EK S/N 182-57438	ANNUAL INSPECTION
	Sim. o. b. 997.97		Per FAR 43 Appendix "D", checked 401576 88-17	
IT 4302.97			PHILLIPSBURG AIR INC. Repair Station CO5-5 601 N. State St. Phillipsburg, Ohio 45154	Emo →
			The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency under work order No. <u>886</u> Signed <u>[Signature]</u> Date <u>9-09-88</u>	


## PROPELLER/ROTOR HISTORY

Propeller/Rotor  
Installed On:

ENGINE TYPE \_\_\_\_\_ MAKE AND MODEL AIRCRAFT \_\_\_\_\_  
 ENGINE SERIAL NUMBER \_\_\_\_\_ AIRCRAFT REGISTRATION NO. \_\_\_\_\_  
 POSITION ( If Multi-Engine Aircraft) \_\_\_\_\_ DATE INSTALLED \_\_\_\_\_

Date	Total Time	Time Since Major Overhaul	Repair Station and Number	Work Performed
10/1/89	4418.67	1113.67	Jal B. Byn AP323269764	- Check prop blades for nicks, leaks & prop spinner/bulkhead
8/5/90	4588.09	1283.09	Jal B. Byn AB323269714	- Replaced spinner bulk head & dynamic balance prop (See engine log)
9-17-91	4791.2			
	AD 91-15-04 COMPLIED WITH PT OVERHAUL 1-17-91 BY KAL AEDS INC. W. Cullen New Services TX 1826115			





**KAL-AERO INC.**

5605 Portage Road  
Kalamazoo, Michigan 49002  
Telephone 616/343-2548  
Telex: 22-4466

X.C.R.S. 3240

C.R.S.# EBVR4500

Home : 517/561-2393  
Office : 517/774-6454 -

W.O.# 02555  
DATE 1/17/91

RANK VOSHELL

CUSTOMER CODE CASHS  
DEPT 19 PROP SHOP  
LABOR RATE QUOTED  
TELEPHONE 616-868-6544  
CONTACT \_\_\_\_\_  
CUST PO# \_\_\_\_\_  
TAX PARTS? Y

REGISTRATION NUMBER \_\_\_\_\_  
AIRCRAFT MAKE / MODEL CE / 182  
AIRCRAFT SERIAL \_\_\_\_\_  
AIRCRAFT UNIT \_\_\_\_\_  
AIRCRAFT TOTAL HOURS UNK \*\*\* 4599.8  
AIRCRAFT TOTAL LANDINGS UNK \*\*\*

FAR PART 121/135 A/C?  
FAR 91.407 CHECK FLIGHT?  
FACTORY WARRANTY ON A/C?

COMPONENT MAKE MCCAULEY  
COMPONENT MODEL 2A34C66ND

COMPONENT PART NO \_\_\_\_\_  
COMPONENT SERIAL 211213

DESCRIPTION OF WORK TO BE PERFORMED -- OVERHAUL PROPELLER

Propeller/Rotor  
Installed On:

ENGINE TYPE \_\_\_\_\_  
ENGINE SERIAL NUMBER \_\_\_\_\_  
POSITION ( If Multi-Engine Aircraft ) \_\_\_\_\_

MAKE AND MODEL AIRCRAFT \_\_\_\_\_  
AIRCRAFT REGISTRATION NO. \_\_\_\_\_  
DATE INSTALLED \_\_\_\_\_

Date	Total Time	Time Since Major Overhaul	Repair Station and Number	Work Performed
4/1/91	TACH	4759.8		
	PROP		OVERHAULLED BY KAL - AERO INC F. Whell 18221246026	
9-10-92	78.3	5 MOH	INSPECTED HUB, BLADES ETC	W. Keller AERO SERVICES

( POSITION ( If Multi-Engine Aircraft )

DATE INSTALLED

ite	Total Time	Time Since Major Overhaul	Repair Station and Number	Work Performed
<p style="text-align: center;">KAL-AERO, INC. PROPELLER LOGBOOK ENTRY</p> <p>N# <u>498EK</u> MAKE <u>McCAULEY</u> MODEL <u>2A34C66-ND</u> S/N <u>711713</u> PAGE <u>1</u> OF <u>1</u> POSITION _____ HOBBS <u>56.8</u></p>				
<p>1. Removed propeller and replaced #2 blade o-ring and lock ring with new. Reserviced with red dye oil. All work done in accordance with McCauley manual # 720415. Reinstalled propeller.</p>				
<p style="text-align: center;">-END-</p>				
<p>The propeller identified on this form was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and only that work performed is approved for return to service. Pertinent details of this repair are on file at this repair station under:</p>				
<p>WORK ORDER # <u>07912</u> DATE <u>09/23/92</u> SIGNED <u>Larry Hickman</u> KAL-AERO, INC. 5605 PORTAGE RD. KALAMAZOO, MI. 49002 CRS # EBVR450D</p>				



Date	Total Time	Time Since Major Overhaul	Repair Station and Number	Work Performed
4-14-94			H & S PROPELLER SHOP, INC. 6220 G-ROW WATERFORD, MI 48327 HQ5ROSON Dawy Seleh 2350075	Disassembled, cleaned inspected, resealed, reassembled, balanced & bench checked.
2/2/96	ACTT 4950.0	790.25		Inspected prop in accordance with an annual inspection using Manufacturer Maint Manual. I certify that this propeller has been inspected in accordance with a annual inspection and was determined to be in satisfactory condition.

appropriate section of this log.

ITA C. 11.11 AP 21171287-IA

MAJOR OVERHAUL

12/07/80 TACH 5170.2

Prop Prep for Repair  
John A. Johnson 1519936 AIC

2003

TACH 518146

Dressed minor nicks @ Both Blades  
I certify that this Prop has been inspected  
in accordance with an annual inspection  
and was determined to be in Airworthy  
condition Stephen Benesh 367621705 #11







DATE	TOTAL TIME IN SERVICE		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
	HOURS	10ths		
1996				
11/17/01	4965	00	Installed school pants. David A. Bullett	371727267
2003			<del>annual inspection complete this date</del> new A/C Battery installed - Gill 35	

### MAINTENANCE RECORD

DATE	TOTAL TIME IN SERVICE		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
	HOURS	10ths		
1996 4/21	4963	.66	Installed Wheel Panto. David A. Bullett	37172-7267
2003			<del>Annual inspection complete this date</del>	
			<del>New A/C Battery installed - Bill 35</del>	
			<del>new non-spike tire and tube installed</del>	
			<del>new Brackett air filter element installed</del>	
			<del>serviced &amp; bled L &amp; R Brake systems,</del>	
			<del>all wheel bearing cleaned &amp; repacked,</del>	
			<del>re-soldered loose wire @ cylinder head temp gauge</del>	
			<del>CFW AD 87-20-03R3 fast track inspection</del>	
			<del>CFW AD 72-03-03R3 flap screw lubrication</del>	

Entered on wrong page 478