

N19JK

PROPELLER LOG #3



The Standard

PROPELLER LOG

Propeller Record General Information

Propeller Manufacturer McCawley

Model B2D34C-208

Hub Series # 755562

Date of Manufacture _____

Type _____

Blade # _____

Aircraft Installed On: Cessna 177B N19JK

Serial # 17701867

HUB & BLADE



SERVICE CENTER

APG Aviation – Maintenance & Repair
28000 Airport Rd. A-17 Punta Gorda, FL 33982
Tel: 941-575-8605 • Fax: 941-575-8734 • ga@avionix.com

Year: _____ Tot in \$

Date: _____

Next Inspection Due: _____ Tin Ovr

09-14-2017 N19JK CESSNA 177B SN 17701867 TTAF 1894.1 TACH 1894.1

CW THE 100hr INSPECTION CHECKLIST IAW CESSNA 177B AMM. INSPECTED HUB, BLADES, SPINNER, AND BACKING PLATE. NO DEFECTS NOTED. OPERATIONAL CHECK SATISFACTORY.

Year: _____ Tot in \$

Date: _____

Next Inspection Due: _____ Tin Ovr

JOE FOUTH *Joe Fouth* TTP 1146.7
3538930 AP TSMOH

Year: _____ Tot in \$

Date: _____

Next Inspection Due: _____ Tin Ovr

I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION IAW CESSNA 177B AMM, FAR PART 43 APP D, AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. APPROVED FOR RETURN TO SERVICE. ADS THRU REV 2017-18.

HARALD R WOLF *Harald R Wolf*

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Switlik Aviation Maintenance, Inc.

Page Field Airport (FMY)

207 Danley Drive

Fort Myers, Florida 33907

239-936-3666

www.switlikaviation.com



Reg. No.	Airframe s/n	Date	Engine s/n	Tach	T.T.	S.M.OH.	Cycles
N19JK	17701867	10/12/2018		1908.7	1908.7		

Model B2D34C-208 S/N 755562 Prop TT 1161.3

Inspected propeller blades, spinner, mount bolts and hub. Ground run and operational checked. I have inspected this propeller in accordance with an Annual Inspection and have found it to be in airworthy condition.

Edward Switlik

IA2197076

Date:

Next Inspection
Due:

Time Since
Overhaul

HUB & BI

PROPELLER

N19jk 17701867 Model B2D34C-208 S/N 75562 Prop TT 1181.93

Year: _____

September 3, 2019

Date: _____

Removed prop dome for inspection. Inspected propeller hub blades and dome I/A/W Cessna

Service Manual 100 HR Annual check list. Replaced dome.

Next Inspection Due: _____

I certify that I have inspected this propeller I/A/W ANNUAL 100 HR Inspection and the the Propeller is in airworthy condition at this time.

Year: _____

L.C. Billingsley, Jr  IA A&P 2195934

Date: _____

Next Inspection Due: _____

Time Since Overhaul

VAN SURDAM VINTAGE AIRCRAFT

SEPTEMBER 23, 2020 N19JK

CESSNA 177B SN 17701867

LYCOMING O-360-A1F6D SN L-17376-36A

McCAULEY B2D34CS SN 755562

TACH: 2119.40 TTAF: 2119.40 TTE: 2119.40 SMOH: 258.6 PROPSMOH: 1372.0

Year: _____


Total Time in Service

Date: _____

Completed an annual inspection per FAR 43 App. D checklist this date. Checked ADs through 2020-18. I certify this prop has been inspected IAW an annual inspection and was found to be in airworthy condition.

Next Inspection Due: _____

Time Since Overhaul



NS

Year: _____
Date: _____
Next Inspection Due: _____

Total in Ser

Time Overt

Year: _____
Date: _____
Next Inspection Due: _____

Total in Ser

Time Overl

Year: _____
Date: _____
Next Inspection Due: _____

Total Time in Service

Time Since Overhaul

PROP MODEL:
B2D34C-208
PROP S/N: 755562
REG NO: 19JK
WORK ORDER: 1644



Aerowood Service Center

3900 Paul J Helms Dr
Monroe, NC 28110
Phone: 704-289-7727

DATE: 9/21/2021
A/C TSN: 2216.28
PROP TT: 2216.28
TSPOH: 2216.28
TACH: 2216.28

Prop Entries

(3) Propeller Annual Inspection Accomplished Propeller Annual inspection.... (9) Spinner bulkhead chaffed.... De burred spinner bulkhead

At owner's request: I Certify that this aircraft has been inspected in accordance with an Annual Inspection using a CHECKLIST in accordance with FAR 43 Appendix D. and Manufacture's Maintenance Manual and was determined to be in airworthy condition. All work was accomplished in accordance with Manufacture's Maintenance Manual and/or AC43.13-1B. AD's verified thru current biweekly. Performed Run up for operation and leak check. All items mentioned have Safeties and are functioning properly at this time.

DATE: 9/21/2021

SIGNED:

Work Order: 1644

Ben Werthwein, IA. 2709574

Printed by EBis 3 (datcomedia.com)

Mech. Cert. # or Repair Station #

Description

Mech. Cert. # or Repair Station #