

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE

TACH
TIME

DESCRIPTION OF WORK

SIGNATURE

SANTA MONICA PROPELLER INC



3025 AIRPORT AVENUE,
SANTA MONICA
CALIFORNIA 90405-6186

FAA REPAIR STATION 4015
TELEX 182028 M PROP SNM
(213) 390-6233

SERVICEABLE PARTS TAG

CUSTOMER Keith Cade & Mark Brown W.O. NO. 10128 DATE 6/20/86

MODEL NO. B2D34C208/82 PA-6 DESCRIPTION McCawley Prop

SERIAL NO. 793823 / K24788, K24804 QUANTITY 1

- | | | |
|---|---|---|
| Completely Overhauled <input checked="" type="checkbox"/> | Angles Corrected <input type="checkbox"/> | Steel Parts Magnafluxed & Cadmium Plated <input checked="" type="checkbox"/> |
| AD's, SB's, SL's Incorporated <input type="checkbox"/> | New Blades Installed <input type="checkbox"/> | Aluminum Hub Penetrant Insp., Anodized <input type="checkbox"/> |
| Part Repaired Only <input type="checkbox"/> | New Electric Deice Installed . <input type="checkbox"/> | Blades Penetrant Insp., Anodized <input checked="" type="checkbox"/> |
| New Seals Installed Only <input type="checkbox"/> | New Alcohol Deice Installed . <input type="checkbox"/> | Blades Penetrant Insp., Anodized <input type="checkbox"/> |
| Blade Damage Repaired <input type="checkbox"/> | Parts Inspected Only <input type="checkbox"/> | Blade Shanks Compression Rolled <input type="checkbox"/> |
| Hub Exchanged w/OHC Unit <input checked="" type="checkbox"/> | AD, SB Compliance Only <input type="checkbox"/> | Blades Edge Trimmed & Painted <input type="checkbox"/> |
| Hub Exchanged w/New Unit <input type="checkbox"/> | Governor RPM Tested & Set <input type="checkbox"/> | Propeller Assembled, Lubricated, Balanced <input checked="" type="checkbox"/> |

REMARKS

Prop removed from a/c.

SEE REVERSE FOR AUTHORIZATION