

Serial 1702  
See original Log  
for prior entries

# PROPELLER MAINTENANCE RECORDS

Log No. \_\_\_\_\_

Aircraft Registration No. N201RZ

Propeller Manufacturer MCCAULEY

Hub Model B2D34C212

Blade Design No. 78CDA-4

Hub Serial No. 773610

Blade Serial No's.

1. K77593
2. K77597
3. \_\_\_\_\_
4. \_\_\_\_\_

Pitch Range:

High \_\_\_\_\_ Low \_\_\_\_\_

Feather \_\_\_\_\_ Reverse \_\_\_\_\_

Governor Manufacturer \_\_\_\_\_

Model No. \_\_\_\_\_

Serial No. \_\_\_\_\_

Date Installed on aircraft \_\_\_\_\_

Time Between Overhauls (TBO) 1500 Hours

If used on multi-engine aircraft:

- |                                |                               |
|--------------------------------|-------------------------------|
| <input type="checkbox"/> Right | <input type="checkbox"/> Left |
| <input type="checkbox"/> Front | <input type="checkbox"/> Rear |

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
------	-----------------------	---------------------------	------------------------------	---

TOTALS brought forward from previous page

NOTE: AD 82-27-02 IS NOT APPLICABLE TO THIS PROP

NOV 84 1622.1 622.1 Removed prop for overhaul.

DATE 1 NOV 84 T/T IN SERVICE 1622.1

D J C Moore  
Signature Repair Station 109-2  
Airframe-Class 3

**PENNSYLVANIA AVIATION, INC.**  
BLUE BELL, PA 19422  
REPAIR STATION 109-2

1-12-84

Overhauled, replaced worn parts  
Work accomplished complies with McCauley  
bulletins through 154 and  
through \_\_\_\_\_  
Blade Ser. No. K77593  
K77597  
Blade Angles Low 14.0  
High 29.5  
Feather 0  
Time since overhaul 0 Total time \_\_\_\_\_

C Ray Hershkey  
For Sensewich Corp  
Jane Pa  
Station 3528

1-15-84 1622.1 0 622.1 Installed overhauled propeller P/W  
B2D34C212 S/W 773610.

THE AIRCRAFT OR COMPONENT IDENTIFIED ON REVERSE SIDE  
OR ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH  
CURRENT REGULATIONS OF THE FEDERAL AVIATION ADMINISTRATION  
AND IS APPROVED FOR RETURN TO SERVICE. (PERTINENT DETAILS  
OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION).

WORK ORDER NO. 8793 DATE 11/15/84  
SUB-TOTALS this page \_\_\_\_\_

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				<b>TOTALS</b> brought forward from previous page
8-15-89	2051	431	1053	CLEANED, DRESSED AND PAINTED PROP.  Jim Mathis 177325019 No P.
1-4-95	229621	674.11	129621	Annual FWS P Completed, Dressed & Painted Prop. No Defects Noted.  Robert O'Donnell AIP 21162
09-01-03	2843.9	1221.8	1816.9	Removed Propeller for O/H Remark. // See # 2311954702
09-16-03	2843.9	<del>1221.8</del>	1816.9	Installed Propeller after O/H by Palm Beach Aircraft Propeller See Attached Tag Dated 9-5-03 w/ # 11437 Checked AD's through issue 2003-18-16 No New Noted: // See # 2311954702
9-19-03	2843.9	<del>1221.8</del>	1816.9	C/W Annual Inspection - AIP 2311954702 EA John Sursey
12-15-04	2860.9	17.0	1860.9	C/W Annual Inspection AIP 2311954702 EA John Sursey
2-3-06	2883.1	39.2	1863.1	C/W Annual Inspection AIP 2311954702 EA
5-4-07	2924	80.1	1897.0	INSPECTED PROPELLER, SPINNER & BRACKING PLATE DURING AIRPORT ANNUAL INSPECTION. Eric Johnson AIP 2632796
7-11-08	2928.1	84.2	1901.1	INSPECTED Prop, Spinner & Brack Plate During Aircraft Annual INSPECTION. Eric Johnson AIP 2632796
3-4-2011	2913.0	96.1	1913.0	INSPECTED Prop, Spinner & Brack Plate During Aircraft Annual
<del>FEB-22-12</del>	<del>2939.0</del>	<del>122.1</del>	<del>1939</del>	INSPECTION - Eric Johnson AIP 2632796
2-22-12	2979.3	122.1	1939	C/W ANNUAL INSP // See # AIP 522990522

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
------	-----------------------	---------------------------	------------------------------	---

Cude Aviation Service  
 PO Box 60133  
 San Angelo, TX 76906-0133

4-11-2013 N201RZ s/n: 24-0327 Tach: 1994.30 **PROPELLER: McCauley B2D34C212 s/n: 773610**  
**TTP: 2994.3 SPOH: 150.40** AD's were checked thru 4-11-2013. For complete list of AD's, see A/C records. I certify that this propeller was inspected in accordance with an annual inspection and was determined to be in an airworthy condition. George Cude Jr IA2691937

*George Cude Jr*

Cude Aviation Service  
 PO Box 60133  
 San Angelo, TX 76906-0133

5-21-2014 N201RZ s/n: 24-0327 Tach: 2047.44 **PROPELLER: McCauley B2D34C212 s/n: 773610**  
**TTP: 3047.44 SPOH: 203.54** AD's were checked thru 5-21-2014. For complete list of AD's, see A/C records. I certify that this propeller was inspected in accordance with an annual inspection and was determined to be in an airworthy condition. George Cude Jr IA2691937

*George Cude Jr*

Cude Aviation Service  
 PO Box 60133  
 San Angelo, TX 76906-0133

8-5-2015 N201RZ s/n: 24-0327 Tach: 2070.88 **PROPELLER: McCauley B2D34C212 s/n: 773610**  
**TTP: 3070.88 SPOH: 226.88** AD's were checked thru 8-4-2015. For complete list of AD's, see A/C records. I certify that this propeller was inspected in accordance with an annual inspection and was determined to be in an airworthy condition. George Cude Jr IA2691937

*George Cude Jr*

Cude Aviation Service  
 PO Box 60133  
 San Angelo, TX 76906-0133

11-17-2017 N201RZ s/n: 24-0327 Tach: 2071.60 **PROPELLER: McCauley B2D34C212 s/n: 773610**  
**TTP: 3071.60 SPOH: 227.60.** AD's were checked thru 11-8-2017. For complete list of AD's, see A/C records. I certify that this propeller was inspected in accordance with an annual inspection and was determined to be in an airworthy condition. George Cude Jr IA2691937

*George Cude Jr*



F.A.A. Approved Repair Station LU4R349M  
JAA Acceptance Certificate #JAA.5271

Aug 29, 2003      Work Order No. 11437      Propeller Mfg. McCauley  
Invoice Number:      Model in: B2D34C212      OUT: B2D34C212  
Exec Air Inc. of Naples      10508      Hub Serial# in: 773610      OUT: 773610  
230 Aviation Drive South  
Naples, FL 34120      Authorized by: JOHN  
Auth. Date: \_\_\_\_\_  
Number: 239-290-5668      Purchase Order # N201RZ      Tail # N201RZ

Model: M20J      Engine Model: IO360A3B6D      TT: UNK  
Instructions:      TSLO: \_\_\_\_\_

Preliminary Inspection:


Appearance      LH      Parts Missing  
Poor      Visual Discrepancies

Information Complied With: Propeller was: Overhaul  
Mfg. Spec. Manual # 780630

As per mandatory Service Information: 137W  
From installation date, next OHC Due: 2000HRS/72MONTHS

Complied with:  
242  
Complied with:  
2003-4

Components Identified were: Overhaul  
in accordance with current FAA regulations  
and were found AIRWORTHY for return to service. Pertinent  
details of the work performed are on file at this agency.

Approved for Service:   
Michael F. O'Neill 2348887      Sep 5, 2003

Complied with: